Figure: 28 TAC §34.1302(b)

Citation	Violation	Fine		Citation	Violation	Fine
6002.152(a)	Branch office registration certificate required	$1,000.00		34.617	Failure to distribute/retain certificate	$500.00
6002.154(a)	No licensed employee	$1000.00		34.618	Installation inspection improperly performed/documented	$50.00-$500.00
6002.154(b)	No license	$3,000.00		34.618	Installation inspection improperly documented	$500.00
6002.154(c)	Licensee not an employee of registered firm	$750.00		34.618	Installation inspection docs not on file for 5 yrs	$500.00
6002.301	Engage in business w/o license or registration certificate	$3,000.00		34.619(a)	System/modification not planned by authorized person	$3,000.00
34.616(b)(4)	Violation of standards established by 34.607	$50.00-$500.00		34.619(b)	Plans not submitted to AHJ	$500.00
34.6616(b)(4)	Violation of standards established by manufacturers requirements (NFPA, 72, §10.3.2)	$50.00-$500.00		34.619(b)	Plans incorrectly submitted to AHJ	$250.00
34.610(a)	Failure to maintain business location	$500.00		34.620(a)	Installation label not affixed to inside of control panel cover	$500.00
34.610(b)	Designated employee	$500.00		34.620(d)	Installation label improperly formatted or incomplete	$500.00
34.610(c)	Registration information not displayed on vehicle	$250.00		34.620(f)	Installation label incorrectly formatted or incomplete (1 or 2 family)	$500.00
34.611(f)(2)	Failure to notify SFMO of termination of employee within 14 days	$250.00		34.621(a)	Service label not affixed to control panel cover	$500.00
34.616(b)(1)	Installation not performed by or	$3,000.00		34.621(b)	Information about yellow or red label not on service	$500.00

	under direct supervision of authorized licensee				label that corrected the impairments	
34.616(b)(1)	Certifying licensee not licensed under ACR of primary registered firm or certifying licensee not present for final acceptance test	$1,000.00		34.623(c) (yellow) 34.624(c) (red	Owner or AHJ not notified of impairment	$500.00
34.616(b)(2)	Licensee attaching label not licensed under ACR of primary registered firm	$1,000.00		34.621(h)	Service label improperly formatted or incomplete	$500.00
34.616(b)(2)	Service and maintenance not performed by or under direct supervision of authorized licensee	$3,000.00		34.622(a)	Inspection/test label not filled out in detail or not affixed to inside of control panel cover	$500.00
6002.302(a)(3)	Misrepresentation of goods or services	$250.00-$1,000.00		34.622(d)	Owner or AHJ not notified of impairment	$500.00
34.610(h); 34.611(d)	Failure to revise or change an address within the required 14 days of change	$250.00		34.622(j)	Inspection/test label incorrectly formatted/incomplete	$500.00
34.616(c)(1)	Monitoring an alarm for an unregistered firm	$3,000.00		34.623(a)	Completed yellow label not attached to outside of control panel of impaired system	$500.00
34.616(c)(2)(A)	Connecting an alarm to an unregistered monitoring firm	$2,000.00		34.623(g)	Yellow label incorrectly formatted/incomplete	$500.00
34.616(3)	No licensed technician at central station	$1,000.00		34.624(a)	Completed red label not attached to outside of impaired system	$1,000.00
				34.624(g)	Red label improperly formatted/incomplete	$500.00

34.613(a)(5)(B)	Lapse of Insurance				
Months	Punitive	+	Amount Saved		Total
0-1	$200	+	$125	=	Warning Letter
1-2	$500	+	$250	=	$750
2-3	$500	+	$375	=	$875
3-4	$500	+	$500	=	$1,000
4-5	$500	+	$625	=	$1,125
5-6	$500	+	$750	=	$1,250
6-7	$750	+	$875	=	$1,625
7-8	$750	+	$1,000	=	$1,750
8-9	$750	+	$1,125	=	$1,875
9-10	$750	+	$1,250	=	$2,000
10-11	$750	+	$1,375	=	$2,125
11-12	$750	+	$1,500	=	$2,250