Figure: 28 TAC §34.1302(a)

Citation	Violation	Fine	Citation	Violation	Fine
	License and Registration		34.517(e)	Fixed system not installed or	\$2,000.00
				serviced by Type A or EPL	
6001.152(Branch office registration	\$1,000.		Installation and Service	
a)	certificate required	00			
6001.161(Apprentice permit	\$500.0	34.517(a)	Portable extinguisher not	\$50.00-
a)	required	0	(1)	installed/serviced/maintained	\$500.00
				IAW manufacturer's	5
				instructions	
6001.251(No registration certificate	\$3,000.	34.517(a)	Service tag not attached upor	\$250.00
a)(1)	(portable)	00	(2)	completion	
				Fixed system not	
				planned/installed/serviced	\$50.00-
6001.251(No registration certificate	\$3,000.	34.517(b	IAW ''manufacturer's	\$500.00
a)(2)	(fixed)	00)(1)	Instructions	
6001.251(No license	\$3,000.	34.517(b	Installation label not affixed	\$250.00
a)(3)		00)(2)	to system upon completion	

34.510(e)(No C registration for U.S.	\$2,000.	34.517(b	Installation label not signed \$500.00
10)(A)	DOT extinguishers	00)(3)	and affixed to system by Type
				A or PL licensee (non pre-
				engineered)
34.510(e)(No verification of U.S. DOT	\$2,000.	34.517(b	Licensee who signed label\$500.00
10)(B)	registration	00)(3)	was not at final test (non
				pre-engineered)
	Registration information			
34.510(f)	not displayed on vehicle	\$250.0	34.517(b	Service tag not attached after\$500.00
		0)(4)	service completion
34.511(f)(Licensee not employed by	\$2,000.	34.517(f)	Pre-engineered kitchen \$2,000.00
1)	registered firm	00		system not UL300
	Failure to notify SFMO of	!		
34.511(f)(termination of employee	\$250.0	34.517(h)	Fusible link manufacturer\$500.00
3)	within 14 days	0		date not within 1 year
34.513	Alteration of certificates,	\$3,000.	34.517(i)	Actuation cartridge not dated \$500.00
	licenses, or permits	00		
34.514(a)(Failure to maintain proof	\$750.0	34.517(j)	Tamper indicator not dated \$500.00
5)(b)	of insurance on file at	0		
	SFMO			
34.510(k);	Failure to revise or change			
34.511(d)	an address within the			
	required 14 days of	\$250.0		
	change	0		

	Adopted Standards		34.518(a)	Shop drawings not on file or\$500.00 not given to owner
	adopted standards or manufacturers portable	\$50.00 - \$500.0		Shop drawings not signed by\$500.00 EPL
	extinguishers Failure to abide by adopted standards or			
1)	manufacturers requirements for fixed			Service tag not completed in \$250.00 detail
	extinguishers Location and Business Practices			Service tag not completed each time service is performed \$500.00
34.510(d)	Failure to maintain business location	\$500.0 0		Owner not notified immediately of impaired \$500.00 portable or fixed extinguisher
34.510(e)	Failure to maintain shop	\$50.00- \$500.0 0	34.521(a)	AHJ not notified within 24 hrs of impaired portable or fixed\$500.00 extinguisher

		\$250.0		Written notice to owner; cop	У
6001.252(Misrepresentation of	0-	34.521(a)	of written notice to AHJ withi	\$500.00
a)(3)	goods or services	\$1,000.		3 days	
		00			
	Pre-engineered system				
34.517(c)	not installed or serviced	\$2,000.	34.521(a)	Failed to attach red tag t	\$500.00
	by authorized licensee	00		impaired extinguisher	
34.517(e)	Fixed system not planned	\$2,000.	34.521(a)	Service tag attached t	\$1,000.00
	by EPL or	00		impaired extinguisher	
	professional engineer				

34.514(a)(5)(B)	Lapse of Insurance					
Months	Punitive	+	Amount saved		Total	
0 - 1	\$200	+	\$125	=	Warning Letter	
1 - 2	\$500	+	\$250	=	\$750	
2 - 3	\$500	+	\$375	=	\$875	
3 - 4	\$500	+	\$500	=	\$1,000	
4 - 5	\$500	+	\$625	=	\$1,125	
5 - 6	\$500	+	\$750	=	\$1,250	
6 - 7	\$750	+	\$875	=	\$1,625	
7 - 8	\$750	+	\$1,000	=	\$1,750	
8 - 9	\$750	+	\$1,125	=	\$1,875	
9 - 10	\$750	+	\$1,250	=	\$2,000	
10 - 11	\$750	+	\$1,375	=	\$2,125	
11 - 12	\$750	+	\$1,500	=	\$2,250	