

Figure: 28 TAC §34.1302(b)

6002.152(a)	Branch office registration certificate required	\$1,000.00		34.617	Failure to distribute/retain certificate	\$500.00
6002.154(a)	No licensed employee	\$1000.00		34.618	Installation inspection improperly performed/documented	\$50.00-\$500.00
6002.154(b)	No license	\$3,000.00		34.618	Installation inspection improperly documented	\$500.00
6002.154(c)	Licensee not an employee of registered firm	\$750.00		34.618	Installation inspection docs not on file for 5 yrs	\$500.00
6002.301	Engage in business w/o license or registration certificate	\$3,000.00				
	Adopted Standards			34.619(a)	System/modification not planned by authorized person	\$3,000.00
34.616(b)(4)	Violation of standards established by 34.607	\$50.00-\$500.00		34.619(b)	Plans not submitted to AHJ	\$500.00
34.6616(b)(4)	Violation of standards established by manufacturers	\$50.00-\$500.00		34.619(b)	Plans incorrectly submitted to AHJ	\$250.00

	requirements (NFPA 72, §10.3.2)					
					Labels	
	Location Business Practices			34.620(a)	Installation label not affixed to inside of control panel cover	\$500.00
34.610(a)	Failure to maintain business location	\$500.00		34.620(d)	Installation label improperly formatted or incomplete	\$500.00
34.610(b)	Designated employee	\$500.00		34.620(f)	Installation label incorrectly formatted or incomplete (1 or 2 family)	\$500.00
34.610(c)	Registration information not displayed on vehicle	\$250.00		34.621(a)	Service label not affixed to control panel cover	\$500.00
34.611(f)(2)	Failure to notify SFMO of termination of employee within 14 days	\$250.00		34.621(b)	Information about yellow or red label not on service label that corrected the impairments	\$500.00
34.616(b)(1)	Installation not performed by (or under direct supervision of) authorized licensee	\$3,000.00		34.623(c) (yellow) 34.624(c) (red)	Owner or AHJ not notified of impairment	\$500.00

34.616(b)(1)	Certifying licensee not licensed under ACR of primary registered firm or certifying licensee not present for final acceptance test	\$1,000.00		34.621(h)	Service label improperly formatted or incomplete	\$500.00
34.616(b)(2)	Licensee attaching label not licensed under ACR of primary registered firm	\$1,000.00		34.622(a)	Inspection/test label not filled out in detail or not affixed to inside of control panel cover	\$500.00
34.616(b)(2)	Service and maintenance not performed by or under direct supervision of authorized licensee	\$3,000.00		34.622(d)	Owner or AHJ not notified of impairment	\$500.00
6002.302(a)(3)	Misrepresentation of goods or services	\$250.00-\$1,000.00		34.622(j)	Inspection/test label incorrectly formatted/incomplete	\$500.00
34.610(h); 34.611(d)	Failure to revise or change an address within the required 14 days of change	\$250.00				
	Monitoring			34.623(a)	Completed yellow label not attached to outside	\$500.00

					of control panel of impaired system	
34.616(c)(1)	Monitoring an alarm for an unregistered firm	\$3,000.00		34.623(g)	Yellow label incorrectly formatted/incomplete	\$500.00
34.616(c)(2)(A)	Connecting an alarm to an unregistered monitoring firm	\$2,000.00		34.624(a)	Completed red label not attached to outside of impaired system	\$1,000.00
34.616(3)	No licensed technician at central station	\$1,000.00		34.624(g)	Red label improperly formatted/incomplete	\$500.00

34.613(a)(5)(B)		Lapse of Insurance			
Months	Punitive	+	Amount saved	=	Total
0 - 1	\$200	+	\$125	=	Warning Letter
1 - 2	\$500	+	\$250	=	\$750
2 - 3	\$500	+	\$375	=	\$875
3 - 4	\$500	+	\$500	=	\$1,000
4 - 5	\$500	+	\$625	=	\$1,125
5 - 6	\$500	+	\$750	=	\$1,250
6 - 7	\$750	+	\$875	=	\$1,625
7 - 8	\$750	+	\$1,000	=	\$1,750
8 - 9	\$750	+	\$1,125	=	\$1,875
9 - 10	\$750	+	\$1,250	=	\$2,000
10 - 11	\$750	+	\$1,375	=	\$2,125
11 - 12	\$750	+	\$1,500	=	\$2,250