

Figure: 28 TAC §34.1302(c)

Citation	Violation	Fine		Citation	Violation	Fine
	Certificates of Registration and Licenses				Planning and Installation	
6003.15 1(a)	Engage in business w/o registration certificate	\$3,000.00		34.717(b))	Failed to maintain copy of updated plans	\$500.00
6003.15 3(b)	Act as responsible managing employee (RME) w/o holding license	\$3,000.00		34.717(c)	Plans do not contain required signatures/ information about firm or licensee	\$500.00
34.710(a))	Subcontracting to unregistered firm to perform work of fire protection sprinkler contractor	\$3,000.00		34.717(c) (2)	Plans not submitted to AHJ for review/permit/rating/record	\$500.00
34.711(a))	Firm's RME not licensed, or license expired	\$1,000.00		34.717(c) (2)	Plans incorrectly submitted to AHJ	\$250.00
34.711(e) (1)	Licensee working not employed by registered firm	\$750.00			Tags	

34.711(e)(2)	Firm failed to notify SFMO of termination of employee w/in 14 days	\$250.00		34.718(a)	Installation tag not completed, not completed in detail, not attached to riser	\$500.00
34.710(g); 34.711(d)	Failure to revise or change an address within the required 14 days of change	\$250.00				
	Adopted Standards			34.718(b)	ITM tag not attached to riser after installation/required tests and inspections	\$500.00
34.716(i)	Planning/installation/service not in accordance with adopted standards	\$50.00-\$500.00		34.719(a)	Service tag not completed and/or not attached to riser	\$500.00
	Location/Business Practices			34.719(c)	New service tag not attached after service	\$500.00
34.710(b)	Failure to maintain business location on certificate of registration	\$500.00		34.719(g)	Service tags improperly formatted	\$250.00
34.711(f)	Individual not licensed for work performed	\$3,000.00		34.720(a)	ITM tag not completed and/or attached to riser after scheduled inspection, testing or maintenance service	\$500.00

34.716(a)	System not installed under supervision of appropriately licensed individual	\$3,000.00		34.720(c)	New ITM tag not completed and attached after each service	\$500.00
34.716(b)	Individual did not affix material and test certificate on or near riser	\$500.00		34.720(g)	ITM tag improperly formatted	\$250.00
34.716(c)	Inspection/test/maintenance service not conducted by appropriately licensed individual	\$3,000.00		34.721(a)	Yellow tag not completed and/or attached to noncompliant system	\$500.00
34.716(d)	Records not available for examination	\$500.00		34.721(c)	Building owner/representative/AHJ not notified of noncompliant system	\$500.00
34.716(e)	Vehicles do not display company name, tel. number and certificate of registration	\$250.00		34.721(f)	Yellow tag improperly formatted	\$250.00
34.716(g)	The planning not performed under the direct supervision of the appropriately licensed RME.	\$500.00		34.722(a)	Red tag not completed and attached to system with an emergency impairment	\$500.00
34.716(h)	Planning, installation, or service of a fire protection sprinkler system not in accord with the minimum	\$3,000.00		34.722(b)	Owner/representative/AHJ not orally notified immediately of impairment	\$500.00

	requirements of the applicable adopted standards				
6003.25 2(3)	Misrepresentation	\$250.00- \$1,000.00	34.722(b)	Owner/representative/AHJ not notified in writing of impairment within 24 hours	\$500.00
	Planning and Installation		34.722(g)	Red tag improperly formatted	\$250.00
34.717(a)	Failed to provide as built plans to the owner	\$500.00			
34.717(a)	Failed to maintain a copy of plans	\$500.00			
34.717(b)	Failed to provide updated plans to owner	\$500.00			

34.713(a)(7)(B)	Lapse of Insurance	
Months	Punitive	+ Amount saved = Total
0 - 1	\$200	+ \$125 = Warning Letter
1 - 2	\$500	+ \$250 = \$750
2 - 3	\$500	+ \$375 = \$875
3 - 4	\$500	+ \$500 = \$1,000
4 - 5	\$500	+ \$625 = \$1,125
5 - 6	\$500	+ \$750 = \$1,250
6 - 7	\$750	+ \$875 = \$1,625
7 - 8	\$750	+ \$1,000 = \$1,750
8 - 9	\$750	+ \$1,125 = \$1,875
9 - 10	\$750	+ \$1,250 = \$2,000
10 - 11	\$750	+ \$1,375 = \$2,125
11 - 12	\$750	+ \$1,500 = \$2,250